Assistant Executive Engineer's Office
PWD, No.2, North Subdivision, Bangalore
PWD, Annex Building 5th Floor
KR Circle Bangalore-01

Tel: 080-221145822
Email: nsdpwd@gmail.com

No:SKA:LOE:No 2:UUV:BEN:AE 2025-26/717

Date: 09/12/2025

For:

The Director,
Vasavi Educational Trust.
No.18, 14th Main,
2nd Phase, J.P Nagar, Bengaluru 560 078.

Dear,

Subject: Regarding issuance of building safety certificate by Vasavi Educational Trust.

Reference: 1) Letter from Vasavi Educational Trust dated: 12-11-2025
2) Government Order No.: Lo.E/59/B.E.D/2019/Date: 06-05-2022.

Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru - 560078 has requested in their letter of reference (1) to issue a building safety certificate stating that the certificate is required for educational purposes. And the documents related to the said building have been submitted to this office.

Accordingly, the school building has been inspected on 05-12-2025 in the presence of the Head, Vasavi Educational Trust. And as per the Government order of reference (2), in the name of The Assistant Executive Engineer, PWD. No 2 North Sub-division, KR Circle, Bangalore, Urban Area, an amount of Rs. 5000/-has been submitted to this office through Khajane-2 in Challan No.: CR1225005900126632.

It is found to be built at Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru -560 078. Regarding the safety of the buildings, & Hydromancy Consultancy Pvt Ltd, #612, Moksha Marga, Siddarta Layout, Mysuru 570011, 5 Rebound hammer test & Ultra Sonic test report have been submitted.

All the documents provided by the said organization have been examined and Hydromancy Consultancy Pvt Ltd, #612, Moksha Marga, Siddarta Layout, Mysuru 570011, has been issued a certificate stating that it is structurally safe. The said reports and the building have been inspected and no cracks have been found in the R.C.C. pillars, beams and roof of the building and the building is found to be safe in appearance. And since the test reports have been found to be in Structural Sound Condition and the building is found to be safe in appearance. It is advised to follow the following conditions.

1. Permission/certificate should be obtained from the competent authorities of the Fire Department and other concerned departments within the stipulated time as per the regulations.

PRINCIPAL
V.E.T. SCHOOL
No. 18, 14th Main, J.P. Nagar
2nd Phase, Bangalore - 560 078

NOTARY ★ ARAVIND PATIL G.G. Reg. No. LAW LGL 213-2020 BENGALURU CITY ★ GOVT. OF KARNATAKA

17 SEP 2026

For V.E.T SCHOOL
President/ Hon. Secretary/ Treasurer

2. The building should be systematically maintained by experts from time to time using high quality materials.

3. The safety of students and teachers should be given utmost priority and appropriate safety measures should be implemented.

4. No other works which may affect the integrity of the building shall be undertaken without the permission of the competent authority. If undertaken without permission, the certificate shall be cancelled immediately.

5. Cleanliness in drinking water and toilets must be maintained at all times and all directions and regulations related to schools and colleges issued by the Bruhat Bengaluru Mahanagara Palike must be followed..

- Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru - 560 078 has been issued a safety certificate for the building for the 2025-2026 academic year.

Yours Faithfully,

-SD-
Assistant Executive Engineer,
PWD., No.2, North Subdivision, Bangalore

Translated from Kannada to English by

NOTARY ★ ARAVIND PATIL G.G. Reg. No. LAW LGL 213-2020 BENGALURU CITY ★ GOVT. OF KARNATAKA

TRANSLATED FROM KANNADA TO ENGLISH 12/9/26
ARAVIND PATIL G.G. B.A., LL B
ADVOCATE & NOTARY
GOVT. OF KARNATAKA
#28, 12th Main, Near Old Sub Register Office
4th Block, Jayanagar Bengaluru - 560 011

17 SEP 2026

PRINCIPAL
V.E.T. SCHOOL
No. 18, 14th Main, J.P. Nagar
2nd Phase, Bangalore - 560 078

For V.E.T SCHOOL
President/Hon. Secretary/Treasurer

Renewal copy.

(19)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಲೋ.ಇ, ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ,ಬೆಂಗಳೂರು
ಲೋ.ಇ, ಅನೆಕ್ಸ್ ಕಟ್ಟಡ 5ನೇ ಮಹಡಿ
ಕೆ.ಆರ್.ವೃತ್ತ ಬೆಂಗಳೂರು-01

(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ದೂರವಾಣಿ: 080-22114582
ಇ ಮೇಲ್: nsdpwd@gmail.com

ಸಂಖ್ಯೆ: ಸಕಾಅ:ಲೋಇ:ನಂ.2:ಉಉವಿ:ಬೆಂ:ಎಇ:2025-26 / 717

ದಿನಾಂಕ: 09/12/2025

ಇವರಿಗೆ:

The Director,
Vasavi Educational Trust,
No.18, 14th Main,
2nd Phase, J.P Nagar,
Bengaluru - 560 078.

ಮಾನ್ಯರೇ,

ವಿಷಯ: Vasavi Educational Trust ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ: 1) Vasavi Educational Trust ರವರ ಪತ್ರ ದಿನಾಂಕ: 12-11-2025
2) ಸರ್ಕಾರದ ಆದೇಶ ಸಂಖ್ಯೆ: ಲೋ.ಇ/59/ಬಿ.ಇ.ಡಿ/2019/ದಿನಾಂಕ: 06-05-2022.

* * * * * *

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru – 560 078 ರವರ V.E.T Manandi P.U & First Grade College ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಶೈಕ್ಷಣಿಕ ಉದ್ದೇಶಕ್ಕಾಗಿ ಒದಗಿಸಲು ಅಗತ್ಯವಿರುವುದಾಗಿ ತಿಳಿಸಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಉಲ್ಲೇಖ (1)ರ ತಮ್ಮ ಪತ್ರದಲ್ಲಿ ಕೋರಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಸದರಿ ಕಟ್ಟಡಕ್ಕೆ ಸಂಬಂಧಿಸಿದ ದಾಖಲೆಗಳನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಲಾಗಿರುತ್ತದೆ.

ಅದರಂತೆ, ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ: 05-12-2025 ರಂದು Vasavi Educational Trust, ಮುಖ್ಯಸ್ಥರ ಉಪಸ್ಥಿತಿಯಲ್ಲಿ ಪರಿವೀಕ್ಷಿಸಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಉಲ್ಲೇಖ (2)ರ ಸರ್ಕಾರದ ಆದೇಶದನ್ವಯ ನಗರ ಪ್ರದೇಶದಲ್ಲಿನ ಶಾಲೆಯ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು The Assistant Executive Engineer, PWD. No 2 North Sub-division, K.R Cirle, Bangalore ರವರ ಹೆಸರಿನಲ್ಲಿ ರೂ. 5000/- ಮೊತ್ತವನ್ನು ಖಜಾನೆ-2 ಮುಖಾಂತರ ಚಲನ್ ಸಂಖ್ಯೆ: CR1225005900126632 ರಲ್ಲಿ ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುತ್ತೀರಿ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru – 560 078 ಜಾಗದಲ್ಲಿ ನಿರ್ಮಿಸಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಕಟ್ಟಡಗಳ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ Hydromancy Consultancy Pvt Ltd, #612, Moksha Marga, Siddarta Layout, Mysuru 570011. ರವರು Rebound hammer test & Ultra Sonic test ಕೈಗೊಂಡು ವರದಿಯನ್ನು ನೀಡಿರುತ್ತಾರೆ.

V.E.T. SCHOOL

For V.E.T. SCHOOL

Principal

PRINCIPAL
V.E.T. SCHOOL
No. 18, 14th Main, J.P. Nagar
2nd Phase, Bangalore - 560 078.

For V.E.T. SCHOOL

President / Hon. Secretary / Treasurer

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಹಾಗೂ Hydromancy Consultancy Pvt Ltd, #612, Moksha Marga, Siddarta Layout, Mysuru 570011, ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಗಳನ್ನು ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡದ ಆರ್.ಸಿ.ಸಿ. ಕಂಬ, ತೊಲೆ ಹಾಗೂ ಛಾವಣಿಯಲ್ಲಿ ಯಾವುದೇ ಬಿರುಕುಗಳು ಕಂಡು ಬಂದಿರುವುದಿಲ್ಲ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಹಾಗೂ ಕಟ್ಟಡವು Structural Sound Condition ಇರುವುದಾಗಿ ಪರೀಕ್ಷೆ ವರದಿಗಳು ಕಂಡು ಬಂದಿರುವುದರಿಂದ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳನ್ನು ಅನುಸರಿಸಲು ಸೂಚಿಸಲಾಗಿದೆ.

1. ಅಗ್ನಿಶಾಮಕ ಇಲಾಖೆ ಮತ್ತು ಇತರೆ ಸಂಬಂಧಪಟ್ಟ ಇಲಾಖೆಗಳ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಗಳಿಂದ ಅನುಮತಿ / ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನಿಯಮಾವಳಿಗಳ ಅನ್ವಯ ನಿಗದಿತ ಸಮಯಗಳಲ್ಲಿ ಪಡೆಯತಕ್ಕದ್ದು.
2. ಕಟ್ಟಡವನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ಉತ್ತಮ ಗುಣಮಟ್ಟದ ಸಾಮಗ್ರಿಗಳನ್ನು ಬಳಸಿ ತಜ್ಞರಿಂದ ವ್ಯವಸ್ಥಿತವಾಗಿ ನಿರ್ವಹಣೆ ಮಾಡತಕ್ಕದ್ದು.
3. ವಿದ್ಯಾರ್ಥಿಗಳ ಹಾಗೂ ಶಿಕ್ಷಕರ ಸುರಕ್ಷತೆಗೆ ಸಕಲ ಆದ್ಯತೆಯನ್ನು ನೀಡಿ ಸೂಕ್ತ ಸುರಕ್ಷತಾ ವ್ಯವಸ್ಥೆಯನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳತಕ್ಕದ್ದು.
4. ಕಟ್ಟಡದ ಸದೃಢತೆಗೆ ಧಕ್ಕೆಯಾಗುವಂತಹ ಯಾವುದೇ ಇತರೆ ಕಾಮಗಾರಿಗಳನ್ನು ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರದಿಂದ ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಳ್ಳತಕ್ಕದ್ದಲ್ಲ. ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಂಡಲ್ಲಿ ಪ್ರಮಾಣ ಪತ್ರವು ಆ ಕೂಡಲೇ ರದ್ದಾಗುತ್ತದೆ.
5. ಕುಡಿಯುವ ನೀರು ಹಾಗೂ ಶೌಚಾಲಯಗಳಲ್ಲಿ ಸದಾ ಸ್ವಚ್ಛತೆಯನ್ನು ಕಾಪಾಡಿಕೊಳ್ಳತಕ್ಕದ್ದು ಹಾಗೂ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯಿಂದ ಶಾಲಾ ಕಾಲೇಜಿಗೆ ಸಂಬಂಧಿಸಿದ ಎಲ್ಲಾ ನಿರ್ದೇಶನ ಹಾಗೂ ನಿಯಮಾವಳಿಯನ್ನು ಕಡ್ಡಾಯವಾಗಿ ಪಾಲಿಸತಕ್ಕದ್ದು.

ಮೇಲೆ ತಿಳಿಸಲಾಗಿರುವ ಷರತ್ತುಗಳಿಗೊಳಪಟ್ಟು Vasavi Educational Trust, No.18, 14th Main, 2nd Phase, J.P Nagar, Bengaluru – 560 078 ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು 2025–2026 ನೇ ಶೈಕ್ಷಣಿಕ ಸಾಲಿನಲ್ಲಿ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಲೋಇ., ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು.

For V.E.T SCHOOL
President/Hon. Secretary/Treasurer

PRINCIPAL
V.E.T. SCHOOL
No. 18, 14th Main, J.P. Nagar
2nd Phase, Bangalore - 560 078